

1. Do you currently have a well located in 20-6W, Rice Co.?

NO, THE WELL IS LOCATED IN SEC 2-21-6W, WHICH IS ON THE TOWNSHIP LINE BETWEEN 20-6W & 21-6W.

2. Is it an Arbuckle SWD?

NO - OPEN HOLE GRANITE WASH WELL, BUT DOES HAVE OTHER DISPOSALS WHICH ARE ARBUCKLE.

3. How often do you perform routine maintenance, or do you have a routine maintenance program?

NO ROUTINE MAINTENANCE FOR A CHEMICAL PROGRAM, BUT DID ROUTINE MAINTENANCE AT LAST MIT 3-4 YEARS AGO, AND REPLACED 3-4 JOINTS OF TUBING.

4. When you do treat the well, how is it treated?

WITH 200-300 GAL 28% HCL, NOT PUMPED IN, BUT GRAVITY FEED

5. What problems do you encounter, which lead to treatment?

BUILD UP OF IRON SULFIDE. IT CAN TAKE A LONG TIME FOR BUILD UP TO HAPPEN BEFORE TREATMENT, 2-3 YEARS. PUMPER WILL SEE A HIGHER FLUID LEVEL IN THE SALTWATER TANK

6. What quantities of product do you use when treating? INDICATING WELL IS NOT TAKING WATER AS FAST.

→ 200-300 GAL

7. Would you have any idea of how much time is spent on location when treating?

45 MIN - 1 HR

8. How are you invoiced?

INVOICE IS MAILED

9. What service company do you usually use in this area?

COPELAND ACID AND CEMENTING. OFFICES IN HAYS, BURTON & GREAT BEND